

Weld measuring




• Determination of the excess thickness of a weld.

Dimensions read on the vernier 1:10^{th.}



• Determination of the apothem or dimension of the centre for a weld angle.


Dimensions read on the vernier 1:10^{th.}



• Evaluation of the angle of a chamfer by comparing the 4 angles on the gauge: 60/70/80/90°

WORK PIECE CONTROL

WELDING GAUGE



DESCRIPTION

The Vernier scale gauge enables to quickly determine the exact dimensions (in mm) of a weld angle, the excess thickness of a weld and the chamfering angle.



Ref: 053977