


INSTRUCTIUNI DE MONTAJ SCAUN DE BIROU OXFORD OC-616


1




2




3



4



5



A		1	H		5
B		1	I		8
C		2	J		4
D		1	K		1
E		1	L		8
F		1			
G		1			